IN 31703

TOR: 09/15303Z JAN 69 DGW

		S E C R E T 090905Z JAN 69 CITE 25X1A
25X1A	de la composition della compos	PRIORITY
25X1A	***	IDEALIST
		1. DURING PAST FEW YEARS 3 KNOWN TURBINE FAILURES HAVE
25X1A	***	OCCURRED. DOES ANY DATA EXIST ON ANY OF THESE
	•	INCIDENTS TO SHOW TIME, HISTORY OF ENGINE RPM AND EGT FOLLOWING
25X1A	-	FAILURE. IF NO DATA AVAILABLE, CAN ANY OF PILOTS INVOLVED
	detect.	RECALL THE RATE OF ENGINE DECAY AND WHETHER OR NOT EGT TENDED TO
		FOLLOW RPM DROP. WE WOULD LIKE TO HAVE ANY SPECIFIC INFORMATION
		ON ANY CASES WHERE EGT REMAINED ABOVE 500 DEGREES C WHILE RPM WAS
25X1A	*** *	FALLING OFF. CAN COMMENT ON ANY TYPE OF ENGINE FAILURE
	-	WHICH WOULD CAUSE EGT TO REMAIN ABOVE 500 DEGREES C WHILE RPM DECAYED
		TO IDLE OR BELOW.
	AMPL.	2. THIS IS NOT INDICATION OF ANY ENGINE PROBLEM ON ART 385
	- water	LOSS NOR DIRECTION INVESTIGATION BOARD POINTED BUT IS FOR INFO TO
	•	CORRELATE AGAINST BW READOUTS.

END OF MSG